

This 2000 Buick Regal was involved in a serious front end collision with a pole. The intrusion (depth of damage) on the Regal is considerable.



Area of Contact Damage with Pole



Area of Contact Damage with Pole

Notice how the area that directly contacted the pole was rounded and pushed inward. Only a collision with a hard cylindrical object can cause this type of damage.