

This 1992 Chevy Blazer was involved in a serious front end collision with a pole. The intrusion (depth of damage) on the Blazer is considerable.



Area of Contact Damage with Pole



Area of Contact Damage with Pole

Notice how the area that directly contacted the pole was rounded and pushed inward. Only a collision with a hard cylindrical object can cause this type of damage.